	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	IS&R	L1	2946	(359/802,803,804,805,808,809, 810,811,812,813,815,817,819,8 22,440,441,442).CCLS.	USPAT; US-PG PUB	2004 /06/ 23 09:2 5			0
2	BRS	L2	583	1 and ((magnif$6 or enlarg$6) with lens$2)	USPAT; US-PG PUB	2004 /06/ 23 09:4 8			0
3	BRS	L3	439	2 and (light$4 or lamp$4 or illuminat$4)	USPAT; US-PG PUB	2004 /06/ 23 09:4 8			0
4	BRS	L4	159	2 and ((light$4 or lamp$4 or illuminat$4) with (pivot$4 or hing$4 or rock$4 or rotat$4 or angl$5))	USPAT; US-PG PUB	2004 /06/ 23 09:4 9			0
5	BRS	L5	107	4 and ((retract$5 or exten$6 or fold$5 or collaps$4 or expan$5 or contract$4) with lens$2)	USPAT; US-PG PUB	2004 /06/ 23 09:2 8			0
6	BRS	L6	2	5 and (rack and pinion$4)	USPAT; US-PG PUB	2004 /06/ 23 09:4 8			0
7	BRS	L7	2	5 and (rack$4 and pinion$4)	USPAT; US-PG PUB	2004 /06/ 23 09:4 0			0
8	BRS	L8	21	1 and (rack$4 and pinion$4 and spring$4)	USPAT; US-PG PUB	2004 /06/ 23 09:4 1			0
9	BRS	L9	6	8 and ((magnif$6 or enlarg$6) with lens$2)	USPAT; US-PG PUB	2004 /06/ 23 09:4 1			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
10	BRS	L10	6	9 and (light$4 or lamp$4 or illuminat$4)	USPAT; US-PG PUB	2004/06/23 09:48			0
11	BRS	L11	184	359/817	USPAT; US-PG PUB	2004/06/23 09:48			0
12	BRS	L13	99	11 and (light$4 or lamp$4 or illuminat$4)	USPAT; US-PG PUB	2004/06/23 09:48			0
13	BRS	L14	42	13 and ((magnif$6 or enlarg$6) with lens$2)	USPAT; US-PG PUB	2004/06/23 09:48			0
14	BRS	L15	3	14 and (rack and pinion$4)	USPAT; US-PG PUB	2004/06/23 09:48			0
15	BRS	L16	21	14 and ((light$4 or lamp$4 or illuminat$4) with (pivot$4 or hing$4 or rock$4 or rotat$4 or angl$5))	USPAT; US-PG PUB	2004/06/23 09:49			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	3091 2	(magnif$6 or enlarg$5) with lens$2	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 08:18			0
2	BRS	L2	16 86 6	1 and (retract$5 or exten$6 or expan$5 or contract$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 07:35			0
3	BRS	L3	54 5	2 and (rack and pinion$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 08:18			0
4	BRS	L4	82 60	1 and ((retract$5 or exten$6 or expan$5 or contract$4) with lens$2)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 08:18			0
5	BRS	L5	0	4 and (pinion$4 with (spring with oil$5))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 07:37			0
6	BRS	L6	0	1 and (pinion$4 with (spring with oil$5))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 07:37			0
7	BRS	L8	1	7 and (rack and pinion$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 08:19			0
8	BRS	L9	22 47 9	1 and (light$5 or lamp$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 07:39			0
9	BRS	L1 0	95 49	1 and ((light$5 or lamp$4) with (pivot$4 or hing$4 or rock$4 or rotat$4 or angl$5))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 08:18			0

	Type	L#	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
10	BRS	L11	303	10 and (rack$4 and pinion$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 07:39			0
11	BRS	L7	6	1 and ((spring with oil$5))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 07:42			0
12	BRS	L12	148	11 and ((retract$5 or exten$6 or expan$5 or contract$4) with lens$2)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 07:42			0
13	BRS	L13	1	12 and ((spring with oil$5))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 07:44			0
14	BRS	L15	52	12 and (switch$4 same (light$5 or lamp$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 08:19			0
15	BRS	L14	34	12 and (switch$4 with (light$5 or lamp$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 08:03			0
16	BRS	L16	17384	(magnif$6 or enlarg$5) near3 lens$2	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 08:18			0
17	BRS	L17	4122	16 and ((retract$5 or exten$6 or expan$5 or contract$4) with lens$2)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 08:18			0
18	BRS	L18	1800	17 and ((light$5 or lamp$4) with (pivot$4 or hing$4 or rock$4 or rotat$4 or angl$5))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/23 08:18			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
19	BRS	L19	70	18 and (rack and pinion$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/ 06/23 08:19			0
20	BRS	L20	24	19 and (switch$4 same (light$5 or lamp$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/ 06/23 08:54			0